

Configuring a Part Number of Gap Filler Type -1

100

G

-

HF2

d

-

Width(mm) × Length(mm)

Thickness

20 = 0.2mm
30 = 0.3mm
50 = 0.5mm
100 = 1.0mm
150 = 1.5mm
200 = 2.0mm
250 = 2.5mm
300 = 3.0mm
350 = 3.5mm
400 = 4.0mm
450 = 4.5mm
500 = 5.0mm

Series

G = GR
X = XR
N = NR
EG = EGR

Construction

blank = Plain Type
F2 = with Nylon Mesh
T2 = with PET Mesh
H = Hardened one Surface
HF2 = Hardened one Surface
with Nylon Mesh
HT2 = Hardened one Surface
with PET Mesh

Variety

ae = GR-ae
d = GR-d
Sd = GR-Sd
e = XR-e
j = XR-j
m = XR-m
Pm = GR-Pm
Pe = XR-Pe
v = XR-v
v-Al = XR-v-Al
Um = XR-Um
Um-Al = XR-Um-Al